

# Bay Area Multihull Association

## 2011 Rating Certificate



The BAMA Ratings Committee has no responsibility for the seaworthiness or safety of yachts rated, but cites US SAILING Fundamental Rule 4, "It shall be the sole responsibility of each yacht to decide whether or not to start or to continue to race."

<b>Boat Name:</b>	Blue Water	<b>PHRF</b>	192 seconds / mile
<b>Sail number:</b>	10105	<b>TCF</b>	TBD
<b>Boat Class:</b>	Seawind 1000XL	<b>Issued</b>	January 11, 2011
<b>Owner Name:</b>	Gary Helms/Mike Ropers		

Source:	Class rules	<input type="checkbox"/>	Sales brochure	<input checked="" type="checkbox"/>	Sailmaker	<input checked="" type="checkbox"/>	Owner measurement	<input type="checkbox"/>
	Designer	<input type="checkbox"/>	BAMA web template	<input type="checkbox"/>	Cut paste	<input type="checkbox"/>	Measurement cert.	<input type="checkbox"/>
This is a(n):	Unmodified class boat	<input type="checkbox"/>	Modified class Boat	<input type="checkbox"/>	Custom boat	<input checked="" type="checkbox"/>	Non-class prod boat	<input type="checkbox"/>

INPUT	Type/Name	Dim.	INPUT	Type/Name	Dim.
Date input			Height – jib		
Weight boat sailing	WS (kg)	5,433	Perpendicular luff jib	lpg	
Draft if no (dagger)boards	Draft (m)	1.00	Area jib (roller furling)	(m <sup>2</sup> )	19.32
Propeller correction	prop		Area – spin 1	(m <sup>2</sup> )	63.17
Overall length (bow-stern)	LOA (m)		Area – spin 2	(m <sup>2</sup> )	
Rated length	RL (m)	10.85	Area – screecher	(m <sup>2</sup> )	TBD
Mast height	(m)	12.19	Calc crew weight	(kg)	
Mast area	(m <sup>2</sup> )				
Height main	p (= vlm)				
Foot length main	e				
Area main	(m <sup>2</sup> )	47.19			

<b>Boat type:</b>	Trimaran	<b>Hull material:</b>	Fiberglass	<b>Motor:</b>	2 x 9.9 OB
<b>Mast:</b>	Aluminum	<b>Mast type:</b>	Fixed round	<b>Rigging:</b>	Stainless wire
<b>Bow pole:</b>	Round steel	<b>Bow pole length:</b>	5' 0"	<b>Beam:</b>	19' 5"
<b>Colors:</b>	<b>Hulls:</b> White	<b>Deck:</b>	White	<b>Nets:</b>	White

**Other Info.** (Describe modifications / Comments / Moveable Ballast / Trapeze, etc., below.)

Owner reported no configuration changes from 2010 except addition of screecher; rating is provisional pending TCF calculation to include screecher.

<b>Home Port</b>	<b>City:</b> Alameda	<b>Marina:</b> Gary Helms' home dock	<b>Slip:</b> N/A
I certify that my vessel conforms to the configuration indicated above and understand that a BAMA ratings certificate will be issued based on this information, valid only for the indicated configuration.			
Signed electronically:	1/04/11		
Mike Ropers			

**This Provisional Certificate Expires June 30, 2011**

Authorized Signature

Jon Green  
 2011 Ratings Chair  
[ratingchair@sfbama.org](mailto:ratingchair@sfbama.org)  
 408-515-7010