

Bay Area Multihull Association BAMA 2010 Rating Certificate



The BAMA Ratings Committee has no responsibility for the seaworthiness or safety of yachts rated, but cites US SAILING Fundamental Rule 4, "It shall be the sole responsibility of each yacht to decide whether or not to start or to continue to race."

Boat Name: **Shadow** PHRF **-99 seconds / mile**
 Sail number: **USA 49** TCF **1.181**
 Boat Class: **Prosail 40 Catamaran** Issued **June 3, 2010**
 Owner Name: **P. Stoneberg**

Source of Information: Class Rules Sales Brochure Sailmaker
 Designer BAMA web template Other Measurement
 This is a: Unmodified Class Boat Modified Class Boat

INPUT	type/name	Prosail 40
date input	slackwater_sf	10/mrt/10
weight boat sailing	WS (kg)	2062
draft if no (dagger)boards	draft	
propeller correction	prop	
overall Length (Length bow to stern)	LOA (m)	12.19
rated length	RL (m)	12.14
area main sail	MSAM (m ²)	88.72
height main	p (= vlm)	20.45
area mast, if rotating wingmast	m ²	7.35
footlength main sail	e	5.56
area jib	MSAG (m ²)	21.74
perpendicular luff jib	lpg	3.12
height jib	l (= vlg)	12.83
area spinnaker	MSAS (m ²)	123.28
Calculated Crew Weight	Not Declared	

Hulls - Material: LOA: 40' LWL: 39.5' Boat type: Catamaran Beam: 22' Min. Draft: 4' (-) Max. Draft: 7'
 Motor/Outboard: Yes 9.9 hp
Hulls Silver Deck Silver Mast Aluminum Nets Silver

Other Info. (Describe modifications / Comments / Moveable Ballast / Trapeze, etc., below.)

Re-issue due to early expiration of June 10, 2010, TCF Texel.AUS.2010

Home Port City: Tiburon Marina: KKMI Point Richmond Slip: Public Area
 I certify that my vessel conforms to the configuration indicated above and understand that a BAMA ratings certificate will be issued based on this information, valid only for the indicated configuration.

signed electronically: 03/09/10
 Peter Stoneberg

This Provisional Certificate Expires January 17, 2011

Authorized Signature

Jon Green
 2010 Ratings Chair
 ratingchair@sfbama.org